

# How to export Gerber files from Altium Designer (Protel) matching Olimex' PCB production

## Design Setup from Altium

### Contents

1. Clearance Setup.....	3
2. Routing Width.....	4
3. Plane Connect.....	4
4. Plane Clearance.....	5
5. Using Polygon Pour.....	5
6. Design Rule Check.....	6
7. Gerber Export.....	7
General Setting.....	8
Layers Setting.....	9
Drill Drawing Setting.....	10
Aperture Setting.....	11
Advanced Setting.....	11
8. CAMtasticx.Cam file.....	13
9. Exporting your drill settings.....	15

### List of Figures

Figure 1 - Clearance Setup.....	3
Figure 2 - Routing Width.....	4
Figure 3 - Plane Connect.....	4
Figure 4 - Plane Clearance.....	5
Figure 5 - Polygon Pour.....	5
Figure 6 - Design Rule Check.....	6
Figure 7 - Gerber Export - Tracks.....	7
Figure 8 - Gerber Setup - General.....	8
Figure 9 - Gerber Setup - Layers.....	9
Figure 10 - Gerber Setup - Drill Drawing.....	10
Figure 11 - Gerber Setup - Apertures.....	11
Figure 12 - Gerber Setup - Advanced.....	12
Figure 13 - Gerber Setup - OK.....	12
Figure 14 - CAMtasticx.Cam file.....	13
Figure 15 - Export Gerber.....	14
Figure 16 - Export Gerber - RS-274-X (extended Gerber).....	14
Figure 17 - Write Gerber(s).....	15
Figure 18 - Exporting Drills.....	15
Figure 19 - NC Drill Outputs.....	16
Figure 20 - NC Drill Setup (Altium Designer 2009).....	16
Figure 22 - Import Drill Data.....	17
Figure 23 - Export NC Drill Files to Gerber.....	17
Figure 24 - Export Gerber(s) - RS-274-X.....	18

## Version History

1.1	<ul style="list-style-type: none"><li>• Figure 20 changed to use “absolute origin”</li><li>• Change format of document</li></ul>
1.0	<ul style="list-style-type: none"><li>• original</li></ul>

# 1. Clearance Setup

Before routing and placing anything be sure to setup clearance to minimum 10mill (Olimex can handle a minimum of 8mill but I had problems even though – a setting of 10 mill has solving the problems.)

This setting can be set in the menu: Design |Rules...




Figure 1 - Clearance Setup

Change this to 10mill as shown by the blue arrow

## 2. Routing Width

Be sure to use minimum 8 mill setting for the Routing Width. This can also be changed in the menu: Design |Rules...




Figure 2 - Routing Width

## 3. Plane Connect

Go to menu: Design |Rules... and choose the setting for Plane | PlaneConnect. Also here be sure to use layer minimum 8 mill.




Figure 3 - Plane Connect

## 4. Plane Clearance

Go to menu: Design | Rules... and choose the setting for Plane | PlaneClearance  
Also here be sure to use minimum 8 mill.




Figure 4 - Plane Clearance

## 5. Using Polygon Pour

When using a copper surface (Polygon Pours) also remember to use minimum of 8 mills here




Figure 5 - Polygon Pour


**NOTE !** The pour needs to be Hatched (made by Tracks and Arcs) instead of a solid copper area.

Remember to set Track Width, Grid Size, Minimum Primitive Length also to minimum 8 mill.  
A setting of 10 mill works every time ☺ !

## 6. Design Rule Check

After finishing the design and before generating the Gerber files you should run a Design Rule check.

This check will use the setting and distances that you have already set up in the previous items following this tutorial.



**Figure 6 - Design Rule Check**

Go to the menu: Tools | Design Rule Check....

Run the check and go no further with gerber files if errors are found.

Read the errors if any – correct them until no further errors are found.

## 7. Gerber Export

To make the Gerber files to the menu: Files | Fabrication Outputs and choose “Gerber Files”




Figure 7 - Gerber Export - Tracks

You will now see 5 pages in the following dialog box

## General Setting

In the General Setting set the precision to 2:4  
(0,1 mill resolution)




Figure 8 - Gerber Setup - General

## Layers Setting

Include the layers that you want to export by marking these




Figure 9 - Gerber Setup - Layers

## Drill Drawing Setting

Mark both layers for Drill Drawing Plots




Figure 10 - Gerber Setup - Drill Drawing

## Aperture Setting

Be sure to mark “Embedded apertures (RS274X)”




Figure 11 - Gerber Setup - Apertures

## Advanced Setting

Be sure to set the Leading/Trailing Zeroes to: “Keep leading and trailing zeroes” and the Position on Film to: “Reference to absolute origin”




Figure 12 - Gerber Setup - Advanced

Now press the button “OK” to go further on.




Figure 13 - Gerber Setup - OK

## 8. CAMtasticx.Cam file

A new page called CAMtasticx.Cam will now arrive showing your PCB.




Figure 14 - CAMtasticx.Cam file

Go selecting menu: File | Export | Gerber...




Figure 15 - Export Gerber

In the dialog box be sure to set these settings




Figure 16 - Export Gerber - RS-274-X (extended Gerber)

Finally Press “OK” and you can select where to put your gerber files for each layer.




Figure 17 - Write Gerber(s)


## 9. Exporting your drill settings

Go back to your design PcbDoc file by pressing the Design page in top of your window




Figure 18 - Exporting Drills

Go to the menu: File | Fabrication Outputs and choose “NC Drill Files”!



**Figure 19 - NC Drill Outputs**

Setup the following showed by the blue arrows



**Figure 20 - NC Drill Setup (Altium Designer 2009)**

Press OK and the following dialog box will be shown




Figure 21 - Import Drill Data

Again press the button “OK”

And another CAM page with all your drillings will be shown. From within this new page Go to the menu: File | Export and choose “Gerber”





Figure 22 - Export NC Drill Files to Gerber

Now we are near the end

A new dialog box will be shown:



**Figure 23 - Export Gerber(s) - RS-274-X**

Check that this has been selected.

NB: Be sure that exactly RS-274-X has been selected !!!!!

(default is RS-274 which are not extended gerbers !!)

Finally press 'OK' save this gerber file and your are ready to email them to Olimex

Using the email: [fastpcb@olimex.com](mailto:fastpcb@olimex.com)

A happy user of Olimex



H.J. Koch 2009  
henrik@koch-engineering.com